




Step 1: locate the three directly specified states




Step 2: regenerator, throttle, and phase separator




Step 3: close the recirculation balance and draw the first stage



Step 4: add the second compression and intercooler



Step 5: complete the high-pressure train



Step 6: complete Linde process and live numerical audit

